

**BUILDING STRUCTURAL SOUNDNESS CERTIFICATE**

This is to certify that I have visited **MONTESSORI (E.M) HIGH SCHOOL**, situated at D. No. **46/1 - L - 1**, A. Camp, Kurnool Mandal, Kurnool district inspected the school building. It is a Pucca building and provided sufficient class rooms. All rooms are in Good Condition, Structurally Sound and well Ventilated.

  
**Asst. Executive Engineer**  
**Mandal Praja Parishad, Kurnool.**